ASSEMBLY INSTRUCTIONS


MODEL: 0289A DRESSER (BOX 1) BOX OF DRESSER NO ITEM QTY DRESSER A 1 pc

METAL LEG

BOTTOM CENTER LEG

4 pcs

1 pc



(BOX 1) HARDWARE LIST

В

 \mathbf{C}

NO	ITEM	QTY
1	Pan Head Chipboard Screw m4x20mm Blk	16 pcs
2	Wood Dowel M6 x 30mm	2 pcs
3	Flat Head Chipboard Screw m4x32mm Rbw	2 pcs



NOTE: MUST TIGHTEN SCREWS PERIODICALLY WITH USE SCREW WILL BECOME LOOSE CHECK TIGHTNESS OF ALL SCREW EVERY 6-8 WEEKS.